Lock 7	Description	Elevation
-1.1	Gage/Land surface per USGS***	503.25
9.3	Normal Low	
21.0	At Top of Bank 1111	
24.5	At the Back Fence Gate 1111	
26.0	Dix Drive begins to flood	
27.5	Dix Drive Impassable with Typical 4-wheel Drive	
27.8	25-04-03 Lock 7 Forecast	
30.0	1st Step Below Stairs Slab 1111	
30.0	Large Portion of Dix Drive floods.	
30.2	on 02-24-2019	
30.8	on 05-19-1995	
31.6	on 02-18-2004	
32.0	on 04-15-2015	
32.0	In 1065 Basement	
33.3	1990	
34.5	on 02-18-2003	
34.5	on 03-21-2002	
35.0	4th Step Down 1111	
36.0	Water enters homes along Dix Drive	
36.5	1924	
37.3	on 03-03-1997	
37.3	on 02-16-2025	
37.9	on 03-01-1962	
37.9	on 03-10-1994	
38.0	At 1111 Garage Concrete Slab	542.5
38.5	on 02-16-1989	
38.6	25-04-04 Lock 7 Forecast	
38.7	on 03-04-2021	
39.0	Dix Drive Floods Completely	
42.2	on 01-23-1937	
42.4	on 04-16-1972	
42.5	25-04-05 Lock 7 Forecast	
43.7	on 05-03-2010	
46.3	Max Level Reached at 1111	
47.1	25-04-06 Max Recorded (Sensor Broken?)	
49.5	25-04-07 (Saw this somewhere)	
52.9	on 01-01-1972	
53.1	on 12-08-1978	
54.0	1111 Floor Level	558.4
	*** I'm off 1.1' = Pretty Close :-)	
	Based on 38' at 1111 Slab	
	If it were really 39' that would work!	
	Green Values are Correct per USGS	

Green Values are Correct per USGS